

Approved For Release 2008/02/05 : CIA-RDP83-00418R007400100003-5

PROCESSING COPY

OOR

3007611


INFORMATION REPORT INFORMATION REPO	1	1	F	0	R	M	A	T		0	Z		RE	P	0	R	T		4	1	F	0	R	N	1	4	1	()	V	F	?	E	P	O	R	2	T
-------------------------------------	---	---	---	---	---	---	---	---	--	---	---	--	----	---	---	---	---	--	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

	C	ENTRAL INTELLIGI	NCE AGENCY		
This mater 18, U.S.C.	rial contains information affecting Secs. 793 and 794, the transmission	the National Defense of the n or revelation of which in	United States within the	meaning of the Espionage Laws, Tit thorized person is prohibited by law	le w.
	,	ONF IDENT IA L			25X1
COUNTRY	Hungary		REPORT		
SUBJECT	Lake Balaton Harbon	r Fecilities	DATE DISTR.	21 November 1956	25 X 1
,			NO. PAGES REQUIREMENT NO.	1 RD	
DATE OF INFO.			REFERENCES		25 X 1
PLACE & DATE ACQ.	SOURĆE EVALUATION	This is UNEVALU	ATED Information		25X1
	Lake Balaton. Harb fuered, and Siofok.	ors discussed are	e those at Balate	on harbor facilities alconfoeldvár, Tihany, Bali the harbor layouts.	25X1 ong aton-
					25X1
				*	
					0
		:			

CONFIDENT IA L/

25X1

STATE	x	ARMY	x	NAVY	х	AIR	x	FBI		AEC		Т	Т		Т		\neg	7
Note: Washington distribution indicated by "X"; Field distribution by "#".)															1			
																 		_



Leonomie

HARBOUR FACILITIES ON LAKE BALATON

BALATON-FOLDVAR

25X1

The harbour at BALATON-FÖLDVAR is only used for small lake steamers carrying passengers and light freight. There are no loading facilities other than a very small mobile crane, capable of lifting no more than 10 cwts. There is a small dockside office for the issue of steamer tickets.

2. A skotch of the harbour is attached as Appendix 'A'.

BALATON-TIHANY

3. Facilities at BALATON-TIHANY are limited to a very simple jetty. There are NO mechanised leading or storage facilities whatever. A sketch of the jetty is attached as Appendix 'B'.

BALATON-FURED

- 4. There is a very simple jetty for the berthing of the lake steamers. There are NO storage facilities on the jetty, and only one very small mobile grane.
- 5. To the West of the jetty there appears to be a small shipperd complex. This consists of a very small slipway, flanked on wither side by a large crane. No building activity was observed on this slipway. There are also two large hanger-

CUNFIDENTIAL

contd/....typo...

25X1

CONFIDENTIAL

25X1

- 2 -

type sheds to the West of this slipway. The shed on the waterfront (see Appendix 'C') contains a slipway, and building activity could be observed in it.

6. The BALATON-FÜRED shippards are stated to build only yachts and a "very few barges".


SIOFOK.


- 7. There is a fairly large shittered harbour at SIOFOK (see Appendix 'D'). Passenger steamers borth in the inner harbour where there are NO leading facilities, except of a purely mobile nature. The outer harbour, which is much larger, has one deckside shed on the East quay, with two medium-sized cranes. No details could be observed of the West quay.
- 8. The SIOFOK Canal loads into the harbour at the South end of the inner harbour. The lock gates and weir appear to be of recent construction. Full details of the lock gates could not be observed, owing to security regulations, but they appeared to be controlled from everhead gantries (see sketch at Appendix 'D').
- 9. The canal itself appears to be in extremely good repair. The sides of the canal have been lined with stone blocks for at least a mile South of SIOFOK. It passes under the read and rail bridges some 200 yards South of the harbour. Both of these are single span girder constructions, resting on two concrete piers. The railway bridge carries a primitive feetpath on its North side.

The canal was under observation for at least an hour on two occasions, and at no time was any traffic seen.

CONFIDENTIAL

25X1





Approved For Release 2008/02/05 : CIA-RDP83-00418R007400100003-5